WA-I- 521 Frame Farmhouse

Late 19th century

Hagerstown Vicinity

Private

The Frame Farmhouse is a two-story, five-bay by three-bay structure covered in aluminum siding. It has a gable roof with a large gable dormer. The main facade has a central entrance with windows in the other four bays on the first story and five bays on the second story. There is a small square window in the front dormer. The house has an L-shaped plan.

Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE __yes __no

		<u> </u>	******		
1. Nam	e (indicate pre	ferred name)			
historic fra	ame farm house	eri	<u>2</u> .		
and/or common					
2. Loca	ation	····			
	The state of the s	5 5 mil	T. 170		
street & number	east side of Rt. o	5, .5 mile south of Hagerst		not for publication	
city, town		x vicinity of	congressional district	sixth	
	yland	county	Washington		
3. Clas	sification				
Category district building(s) structure site object	Ownership public private both Public Acquisition in process being considered not applicable	Status occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:	
4. Own	er of Proper	ty (give names and	l mailing addresse	s of <u>all</u> owners)	
name Lest	ter Shimp				
street & number	-		telephone no	. •	
Street & Hulliper	 				
city, town	- 4		nd zip code		
5. Loca	ation of Lega	al Descriptio	<u>n</u>		
courthouse, regi	stry of deeds, etc. Was	hington County Court	house	liber 561	
street & number	Washington Street			folio 567	
city, town	Hagerstown		state	Maryland	
6. Rep	resentation	in Existing	Historical Surv	eys	
itle					
	·				
date			federal stat	e county loca	
depository for su	urvey records		-		

Survey No. WA-I-501 52/

deteriorated ruins unexposed	Check one unaltered altered	Check one original si moved	ite date of move	

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame farmhouse is a two-story, five-bay by three-bay structure covered in aluminum siding. It has a gable roof with a large gable dormer. The main facade has a central entrance with windows in the other four bays on the first story and five bays on the second story. There is a small square window in the front dormer. The house has an L-shaped plan. It appears to have been constructed in the late 19th century.

The frame farmhouse is located on the east side of Rt. 65, .5 mile south of I-70. It sits on a small rise just off the main highway in the vicinity of two earlier farmsteads.

The farmhouse currently has a modern aluminum siding on the exterior. It also has modern exterior concrete block flue is on the northernmost gable end of the building. The gable roof is covered in asphalt shingles. The windows throughout the house are one-over-one pane sash windows. The only ornamentation on the house is the turned posts on the full-length, one-story porch.

The property contains no significant outbuildings, but does contain several small buildings including a garage and shed.

1400 1500	0–1599 agriculture 0–1699 architecture 0–1799 art 0–1899 commerce	community planning conservation conservation conservation conservation conservation conservation conservation conservation/settlement conservation conserva	literature military music philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	: dates	Builder/Architect		
check:	Applicable Criteria:A and/or Applicable Exception:A Level of Significance:	A _B _C _D _E		
		nacionac state	TOCAL	

Based on the MHT Survey Matrix, this is a mid-level site. It is a representative late 19th century farmhouse for this region. Its architectural intregrity has been diminished by application of modern siding and removal of period ornamentation.

10.	Geographic	al Data			
Quadran	of nominated property gle name ferences do NOT comp1			Qua	drangle scale
AZone			B Zone	Easting	Northing
C E G			D		
Verbal	boundary description and	d justification			
	states and counties for			ounty bound	
state state		code	county	·	code
11.	Form Prepa	red By			
name/titl	e Joe Getty				
organiza	tion Maryland Histo	rical Trust	da	ate May	1983
street &	number 21 State Cir	cle	te	lephone	
city or to	wn Annapolis		et	ate Mary	l and

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438



- 1. Frame Farmhouse WA-I-501 58/
- 2. Washington County, Maryland
- 3. Joe Getty
- 4. May 1983
- 5. Maryland Hist. Trust, Annapolis, Md.
- 6. West facade; camera facing east
- 7. 1/1